



Inspection Overview

Unit Name	Gladiator Duel	Inspected by	David Tofton (RPII Inspector No 96)
Description	Yellow and black mini wall gladiator duel with Velcro podiums	Manufacturer	Cream Castles
Size (m)	Width: 5.5 Length: 5.5 Height: 0.95	Controller / Owner	Cream Castles
Manufacturer Serial Number	C53	Issued Date	29 June, 2026

Risk Assessment

Open inflatable - caution should be used - no bouncing - the bed is for catching the users.

Assessment Results

User Height/Count

Main Wall Height (m): 0.4
Mini wall
Play Area Length (m): 3.5
Play Area Width (m): 3.5
Negative Play Space Adjustment (m²): 1.0
Users at 1m: 2
Users at 1.2m: 2
Users at 1.5m: 2
Users at 1.8m: 2
Custom User Height
As recommended by
Manufacturer/importer

Structure

[PASS] Seam Integrity
[PASS] Stitching
Pulling in the corners - monitor
[PASS] Air Loss
[PASS] Vertical Walls (+/- 5%)
[PASS] Sharp Angles or Edges
[PASS] Unit Stability

[PASS] Evacuation Time (s)
[PASS] Step/Ramp Size (mm): 950
No Step - use mats on all open sides
[PASS] Platform Height (mm): 950
[PASS] Fall Off Height (mm): 950
Caution should be used - mats are required on all open sides
[PASS] Unit Pressure (kpa): 1.4
Trough Depth (mm): 40
Trough Adjacent Panel Width (mm): 550
[PASS] Trough Check
[PASS] Entrapment
[PASS] Markings
[PASS] Grounding
Anchorage
[PASS] Low anchor points: 8
[PASS] High anchor points: 0
[PASS] Correct anchor accessories
[PASS] Anchors between 30-45°
[PASS] Anchors permanently closed and metal
[PASS] Pull strength test

Materials

[N/A] Ropes (mm)
[N/A] Retention netting
[PASS] Zips
[N/A] Windows
[N/A] Artwork
[PASS] Thread
Manufacturer/importer
[PASS] Fabric strength
Manufacturer/importer
[PASS] Fire retardent
Manufacturer/importer
Fan/Blower
Blower sizes: 2Hp
Number of blowers: 1
Blower serial numbers: 202450851
[PASS] Blower Tube Length (m): 1.2
Caution: open-sided inflatable
[PASS] Return flaps present
[PASS] Finger probe tests
[PASS] PATs
01/01/2026

[PASS] Visual inspections



Disclaimer

I confirm that I inspected this inflatable device and that all details contained within this inspection report are a true representation of what I found and observed during my inspection process.

Signature

Photos



Photo 1



Photo 2



Photo 3